



The Great Lakes - St. Lawrence Seaway System
Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2008 – Notice to Shipping N° 9

MAISONNEUVE REGION

MONTREAL / LAKE ONTARIO SECTION

Security at approach / tie-up walls

Mariners are reminded that Seaway approach/tie-up walls are not considered restricted or controlled areas under the SLSMC, Transport Canada approved Facilities Security Plan.

Seaway approach/tie-up walls are monitored by camera when feasible. Should there be security concerns at these locations, mariners are requested to provide details to Seaway operations centre who will initiate security response measures.

If a ship conducts an interface at a Seaway approach/tie-up wall, the Seaway operations centre must be advised ahead of time and all security measures are the responsibility of the ship with the supplier or visitor.

Any person who approaches the site of an interface must be challenged.

August 12, 2008

The St. Lawrence Seaway Management Corporation
Corporation de Gestion de la Voie Maritime du Saint-Laurent

Région Maisonneuve
151, rue de l'Écluse
St-Lambert, Québec
J4R 2V6

Tél : (450) 672-4115 Fax : (450) 672-8493

Niagara Region
508 Glendale Avenue
P.O. Box 370
St-Catharines, Ontario
L2R 6V8

Tél : (905) 641-1932 Fax : (905) 641-5721