



The Great Lakes - St. Lawrence Seaway System
Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2013 – Notice to Shipping # 23

MAISONNEUVE REGION
MONTREAL / LAKE ONTARIO SECTION

Section of fendering missing at the Côte Sainte-Catherine upper approach wall

Mariners are advised that an approximate 4 meters section of fendering is missing abeam of bollard n° 25 at the upper Côte Sainte-Catherine lock approach wall. It is recommended that this part of the approach wall be avoided.

The missing section will be replaced by September 6, 2013.

Maisonneuve Region
August 27, 2013

The St. Lawrence Seaway Management Corporation
Corporation de Gestion de la Voie Maritime du Saint-Laurent

Région Maisonneuve
151, rue de l'Écluse
St-Lambert, Québec
J4R 2V6

Tél : (450) 672-4115 Fax : (450) 672-8493

Niagara Region
508 Glendale Avenue
P.O. Box 370
St-Catharines, Ontario
L2R 6V8

Tél : (905) 641-1932 Fax : (905) 641-5721