



**The Great Lakes - St. Lawrence Seaway System**  
***Le réseau Grands Lacs - Voie maritime du Saint-Laurent***

---

2010 – Notice to Shipping N° 4

MAISONNEUVE REGION

MONTREAL / LAKE ONTARIO SECTION

### Security at approach / tie-up walls

Mariners are reminded that Seaway approach/tie-up walls are not considered restricted or controlled areas under the SLSMC, Transport Canada approved Facilities Security Plan.

Seaway approach/tie-up walls are monitored by camera when feasible. Should there be security concerns at these locations, mariners are requested to provide details to Seaway operations centre who will initiate security response measures.

If a ship conducts an interface at a Seaway approach/tie-up wall, the Seaway operations centre must be advised ahead of time and all security measures are the responsibility of the ship with the supplier or visitor.

Any person who approaches the site of an interface must be challenged.

April 14, 2010

---

**The St. Lawrence Seaway Management Corporation**  
**Corporation de Gestion de la Voie Maritime du Saint-Laurent**

**Région Maisonneuve**  
151, rue de l'Écluse  
St-Lambert, Québec  
J4R 2V6

Tél : (450) 672-4115 Fax : (450) 672-8493

**Niagara Region**  
508 Glendale Avenue  
P.O. Box 370  
St-Catharines, Ontario  
L2R 6V8

Tél : (905) 641-1932 Fax : (905) 641-5721