

2012 – Notice to Shipping # 1

MAISONNEUVE REGION MONTREAL / LAKE ONTARIO SECTION

Security at approach / tie-up walls

Mariners are reminded that Seaway approach/tie-up walls are not considered restricted or controlled areas under the SLSMC, Transport Canada approved Facilities Security Plan.

Seaway approach/tie-up walls are monitored by camera when feasible. Should there be security concerns at these locations, mariners are requested to provide details to Seaway operations centre who will initiate security response measures.

If a ship conducts an interface at a Seaway approach/tie-up wall, the Seaway operations centre must be advised ahead of time and all security measures are the responsibility of the ship with the supplier or visitor.

Any person who approaches the site of an interface must be challenged.

March 20, 2012

The St. Lawrence Seaway Management Corporation Corporation de Gestion de la Voie Maritime du Saint-Laurent