



**The Great Lakes - St. Lawrence Seaway System**  
*Le réseau Grands Lacs - Voie maritime du Saint-Laurent*

---

2020 – Notice to Shipping #19

MAISONNEUVE REGION

MONTRÉAL / LAKE ONTARIO SECTION

## Modifications to Ship Inspections - Revised

This Notice supersedes Notice to Shipping #11. The need to submit the “IMO Health Declaration Form” was removed.

Due to the current operating environment, temporary changes to the Seaway Enhanced Ship Inspections (ESI) program for foreign ships are being implemented in order to minimize the risk of exposure, while balancing the risk to Seaway structures and ensuring compliance with Seaway Practices and Procedures.

These temporary measures will pro-actively evaluate ship's conditions based on historical transits, the date of the last Seaway inspection, past deficiencies and corrective actions, etc. Ships that would traditionally be inspected will be sent a “**Self-Inspection Report for Foreign Ships**” ([PDE](#) | [DOC](#)) which must be filled out and returned to SLSMC 96 hours prior to arrival at CIP 2. This evaluation may result in some ships being exempt from a full ESI and they will be granted direct entry into St-Lambert Lock.

For exempt ships that may have a direct entry to the Seaway, ballast water inspections will still occur, however they will either take place between St-Lambert Lock and Cote St-Catherine Lock, between Snell Lock and Eisenhower Lock, or through other administrative measures.

These temporary measures will be in place until further notice.

Maisonneuve Region  
April 3, 2020

---

**The St. Lawrence Seaway Management Corporation**  
**Corporation de Gestion de la Voie Maritime du Saint-Laurent**

**Région Maisonneuve**  
151, rue de l'Écluse  
St-Lambert, Québec  
J4R 2V6

Tél : (450) 672-4115 Fax : (450) 672-8493

**Niagara Region**  
508 Glendale Avenue  
P.O. Box 370  
St-Catharines, Ontario  
L2R 6V8

Tél : (905) 641-1932 Fax : (905) 641-5721