



The Great Lakes - St. Lawrence Seaway System
Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2020 – Notice to Shipping #24

MAISONNEUVE REGION

MONTREAL / LAKE ONTARIO SECTION

Restrictions for Pilots Boarding Ships at Iroquois Lock - Revised

In order to minimize the risk to exposure of COVID-19, pilots are to head directly to the waiting area provided on the lower end bullnose at Iroquois Lock and remain there until the ship is secured. Pilots are to approach the ship only once SLSMC personnel have completed securing the ship in the lock.

A minimum social distancing of 2 meters is required at all times between the pilot and SLSMC personnel.

Taxi drivers and pilots will be subject to the SLSMC screening measures before being allowed onto the lock. They may be refused access to the lock should they not meet the screening criteria. Taxi drivers are not permitted to exit their vehicles.

We ask that you respect these guidelines to protect everyone's safety. Thank you for your understanding and cooperation.

May 6, 2020

The St. Lawrence Seaway Management Corporation
Corporation de Gestion de la Voie Maritime du Saint-Laurent

Région Maisonneuve
151, rue de l'Écluse
St-Lambert, Québec
J4R 2V6

Tél : (450) 672-4115 Fax : (450) 672-8493

Niagara Region
508 Glendale Avenue
P.O. Box 370
St-Catharines, Ontario
L2R 6V8

Tél : (905) 641-1932 Fax : (905) 641-5721