



The Great Lakes - St. Lawrence Seaway System
Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2020 – Notice to Shipping #11

MAISONNEUVE REGION

MONTRÉAL / LAKE ONTARIO SECTION

Modifications to Ship Inspections (Cancelled 2020/04/03)

Due to the current operating environment, temporary changes to the Seaway Enhanced Ship Inspections (ESI) program for foreign ships are being implemented in order to minimize the risk of exposure, while balancing the risk to Seaway structures and ensuring compliance with Seaway Practices and Procedures.

These temporary measures will pro-actively evaluate ship's conditions based on historical transits, the date of the last Seaway inspection, past deficiencies and corrective actions, etc. Ships that would traditionally be inspected will be sent a "Self-Inspection Report for Foreign Ships" ([PDF](#) | [DOC](#)) which must be filled out and returned to SLSMC 96 hours prior to arrival at CIP 2. This evaluation may result in some ships being exempt from a full ESI and they will be granted direct entry into St-Lambert Lock. In addition to the "Self-Inspection Report for Foreign Ships" the SLSMC requests that the "IMO Health Declaration Form" also be submitted.

For exempt ships that may have a direct entry to the Seaway, ballast water inspections will still occur, however they will either take place between St-Lambert Lock and Cote St-Catherine Lock, between Snell Lock and Eisenhower Lock, or through other administrative measures.

These temporary measures will be in place until further notice.

Maisonneuve Region
March 25, 2020

The St. Lawrence Seaway Management Corporation
Corporation de Gestion de la Voie Maritime du Saint-Laurent

Région Maisonneuve
151, rue de l'Écluse
St-Lambert, Québec
J4R 2V6

Tél : (450) 672-4115 Fax : (450) 672-8493

Niagara Region
508 Glendale Avenue
P.O. Box 370
St-Catharines, Ontario
L2R 6V8

Tél : (905) 641-1932 Fax : (905) 641-5721