

The Great Lakes - St. Lawrence Seaway System Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2019 – Notice to Shipping #31
MAISONNEUVE REGION
MONTREAL / LAKE ONTARIO SECTION

Revised Ship Speed Restriction - Brockville Narrows to Prescott (Cancelled 2019/10/01)

This notice rescinds Notice to Shipping No. 27 of 2019.

As water levels have decreased considerably since the implementation of this speed restriction, Mariners are advised that the speed restriction for upbound ships has been revised.

Between buoy 132 and light 147:

- **Upbound ships are now limited to 10.5 knots** (Column IV of Schedule II Table of Speeds) in the Seaway Handbook Practices & Procedures)
- **Downbound ships continue to be limited to 10.5 knots** (Column IV of Schedule II Table of Speeds) in the Seaway Handbook Practices & Procedures)

Ship speeds will be monitored closely and there will be zero tolerance for ships exceeding the speed limit.

Mariners are also reminded to watch their wake, particularly when navigating close to shore.

We will continue to closely monitor the conditions and inform you of any change.

Maisonneuve Region September 12, 2019

Tél: (905) 641-1932 Fax: (905) 641-5721