

SEAWAY NOTICE NO. 5 – 2016

Notification Requirement for Use of Wires at HFM Locks

If a need to use wires is identified at locks where HFM is installed, for reasons such as equipment malfunction (e.g. bow thruster, engine), HFM equipment out of service, HFM incompatibility, a need for tie-up service, ice covered hulls or other weather conditions, an **advance notice of at least 60 minutes** identifying the need shall be provided, when possible.

- If the need is identified by Seaway personnel, traffic control will advise the vessel.
- If the need is identified by the vessel, then the vessel is to advise the traffic control center.

March 10, 2016