




The Great Lakes - St. Lawrence Seaway System
Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2010 - Notice to Shipping # 27

MAISONNEUVE REGION
MONTREAL / LAKE ONTARIO SECTION

Anchor lost in main channel on Lake St-Francis below St-Zotique anchorage

A stern anchor has been lost above buoy D5 in the main channel on Lake St Francis. The reported position is as follows:



45 degrees 13.72 min North and 73 degrees 12.68 min West

During the search and recovery period, we are asking that mariners do not transit over the position given and do not meet, or exceed 10 knots, the area a half mile above and below D5.

Maisonneuve Region
October 21, 2010

The St. Lawrence Seaway Management Corporation
Corporation de Gestion de la Voie Maritime du Saint-Laurent

Région Maisonneuve
151, rue de l'Écluse
St-Lambert, Québec
J4R 2V6

Tél : (450) 672-4115 Fax : (450) 672-8493

Niagara Region
508 Glendale Avenue
P.O. Box 370
St-Catharines, Ontario
L2R 6V8

Tél : (905) 641-1932 Fax : (905) 641-5721