



The Great Lakes - St. Lawrence Seaway System
Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2010 - Notice to Shipping # 30

MAISONNEUVE REGION
MONTREAL / LAKE ONTARIO SECTION

Anchor moved out of main channel on Lake St-Francis below St-Zotique anchorage

A stern anchor has been moved out of the main channel. Anchor position is now 200 feet north of buoy D6. Conditions imposed in Notice to Shipping #27 are no longer applicable. Speed for this region is as per published in Seaway handbook.

Maisonneuve Region
November 11, 2010

The St. Lawrence Seaway Management Corporation
Corporation de Gestion de la Voie Maritime du Saint-Laurent

Région Maisonneuve
151, rue de l'Écluse
St-Lambert, Québec
J4R 2V6

Tél : (450) 672-4115 Fax : (450) 672-8493

Niagara Region
508 Glendale Avenue
P.O. Box 370
St-Catharines, Ontario
L2R 6V8

Tél : (905) 641-1932 Fax : (905) 641-5721