



The Great Lakes - St. Lawrence Seaway System
Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2011 – Notice to Shipping # 11

MAISONNEUVE REGION
MONTRÉAL / LAKE ONTARIO SECTION

Morrisburg Water Levels

Mariners are advised that the water levels at Morrisburg have returned to normal. The speed limits for vessels between Eisenhower and Iroquois locks will now be applied as per column III of the Seaway Handbook.

Mariners are also advised to watch their wakes as high water levels are still present between Iroquois and Lake Ontario.

Maisonneuve Region
June 21, 2011

The St. Lawrence Seaway Management Corporation
Corporation de Gestion de la Voie Maritime du Saint-Laurent

Région Maisonneuve
151, rue de l'Écluse
St-Lambert, Québec
J4R 2V6

Tél : (450) 672-4115 Fax : (450) 672-8493

Niagara Region
508 Glendale Avenue
P.O. Box 370
St-Catharines, Ontario
L2R 6V8

Tél : (905) 641-1932 Fax : (905) 641-5721