



The Great Lakes - St. Lawrence Seaway System
Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2012 – NOTICE TO SHIPPING #9

MAISONNEUVE REGION
MONTREAL/LAKE ONTARIO SECTION

WATER LEVELS ON LAKE ST-LOUIS

The water levels on Lake St-Louis being close to Seaway alert levels, we are asking mariners to avoid sailing over and SOUTH of the following positions:

Two positions at 450 and 560 meters EAST of buoy A33 and at 80 meters NORTH of the SOUTH canal line.

- 45 degrees 22.34 minutes NORTH 73 degrees 49.38 minutes WEST
- 45 degrees 22.31 minutes NORTH 73 degrees 49.43 minutes WEST

Also avoid sailing over and NORTH of the following positions:

At 300 meters EAST of buoy A35 and 35 meters SOUTH of the NORTH canal line

- 45 degrees 21.96 minutes NORTH 73 degrees 49.97 minutes WEST

At 130 meters WEST of buoy A38 and 30 meters SOUTH of the NORTH canal line.

- 45 degrees 21.57 minutes NORTH 73 degrees 50.55 minutes WEST

We will advise you of any further changes.

Maisonneuve Region
June 1, 2012

The St. Lawrence Seaway Management Corporation
Corporation de Gestion de la Voie Maritime du Saint-Laurent

Région Maisonneuve
151, rue de l'Écluse
St-Lambert, Québec
J4R 2V6
Tél : (450) 672-4115
Fax : (450) 672-8493

Niagara Region
508 Glendale Avenue
P.O. Box 370
St-Catharines, Ontario
L2R 6V8
Tél : (905) 641-1932
Fax : (905) 641-5721