



The Great Lakes - St. Lawrence Seaway System
Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2013 – Notice to Shipping #37

MAISONNEUVE REGION

MONTRÉAL / LAKE ONTARIO SECTION

Water Levels on Lake St-Louis

Mariners are advised that outflow from Lake Ontario will be reduced due to ice formation, resulting in declining water levels on Lake St-Louis. For this reason, the speed limit between buoys A30 and A40 are reduced as follows:

- Vessels with a draft greater than 70 dm are limited to 11 knots upbound and 13 knots downbound.

For vessels with a draft of 70 dm or less, the speed limit remains limited to 12 knots upbound and 14 knots downbound respectively.

We will continue to monitor the outflow, as further reductions are expected, and advise you of any other changes.

Maisonneuve Region

December 13th, 2013

The St. Lawrence Seaway Management Corporation
Corporation de Gestion de la Voie Maritime du Saint-Laurent

Région Maisonneuve
151, rue de l'Écluse
St-Lambert, Québec
J4R 2V6

Tél : (450) 672-4115 Fax : (450) 672-8493

Niagara Region
508 Glendale Avenue
P.O. Box 370
St-Catharines, Ontario
L2R 6V8

Tél : (905) 641-1932 Fax : (905) 641-5721