



The Great Lakes - St. Lawrence Seaway System
Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2020 – Notice to Shipping N° 20
MAISONNEUVE REGION
MONTREAL / LAKE ONTARIO SECTION

Removal of Tug at Iroquois Lock

Mariners are advised that navigation conditions were evaluated following the recent decrease in outflows from Lake Ontario and conditions are such that a tug is no longer deemed necessary at Iroquois Lock.

Effective April 7, 2020 at 06h00, the tug will no longer be available to assist ships with their approach at Iroquois Lock.

Conditions will be monitored closely. As outflows start to increase, the feedback from mariners will be sought in order to determine the need for tug assistance once again.

Maisonneuve Region
April 6, 2020