

NOTICE TO SHIPPING NO. 3 - 2023

MAISONNEUVE REGION MONTREAL / LAKE ONTARIO SECTION

Speed Restrictions - MLO Section (Cancelled 2023/04/25)

In addition to the speed limits outlined in the Seaway Practices & Procedures Schedule II - Table of Speeds, the following speed restrictions are also in effect in the MLO section:


LOCATION	RESTRICTION
Galop Island, between LB122 & LB127	 8 knots (upbound) for ships drafting greater than 78.0dm
Sector IV, between buoys LB157 & LB162	 8.5 knots (upbound) for ships drafting greater than 78.0dm

*Ship speeds in the above areas will be monitored closely.

GALOP ISLAND - HIGH SPOTS

Ships drafting greater than 78.0 dm are advised to **avoid meets and sailing over** the Galop Island high spots located at the following coordinates:

- High Spot A: 44° 45.6693'N 075° 24.8710'W
- High Spot B: 44°45.9575'N 075°24.4942'W



The St. Lawrence Seaway Management Corporation Corporation de Gestion de la Voie Maritime du Saint-Laurent 202 Pitt Cornwall, Ontario K6J 3P7 Tel: 613-932-5170

Great Lakes St. Lawrence Seaway Development Corporation 180 Andrews Street Massena, New York 13662 Tel: 315-764-3200



SECTOR IV - HIGH SPOTS

Upbound ships drafting greater than 78.0 dm are to avoid ship meets and sailing over the high spots identified below:

- Above Cross Over Island Call In Point: 44°29.5947'N 75°46.5212'W
- Above North Colborne Island: 44° 15.4103' N 76° 4.226' W

Conditions will be monitored closely and Mariners will be advised of any changes.

March 15, 2023