

NOTICE TO SHIPPING NO. 10 - 2024

MAISONNEUVE REGION MONTREAL / LAKE ONTARIO SECTION

SPEED RESTRICTIONS - MLO SECTION – Revision #2 (revised 2024/09/18)

Due to recent precipitation and an increase of water levels, certain restrictions have been revised.

In addition to the speed limits outlined in the Seaway Practices & Procedures Schedule II - Table of Speeds, the following speed restrictions are also in effect in the MLO section:

LOCATION	RESTRICTIONS	
	UPBOUND	DOWNBOUND
Galop Island, between LB122 & LB127	• <u>Revised to 8 knots</u> for ships drafting greater than 78.0dm	<u>Revised to: N/A</u>
Sector IV, between buoys LB157 & LB162	• 8.5 knots for ships drafting greater than 78.0dm	N/A


*Ship speeds in the above areas will be monitored closely.

GALOP ISLAND - HIGH SPOTS

Ships drafting greater than 78.0 dm are advised to **avoid meets and sailing over** the Galop Island high spots located at the following coordinates:

- High Spot A: 44° 45.6693'N 075° 24.8710'W
- High Spot B: 44°45.9575'N 075°24.4942'W





SECTOR IV – HIGH SPOTS

Upbound ships drafting greater than 78.0 dm are to avoid ship meets and sailing over the high spots identified below:

- Above Cross Over Island Call In Point: 44°29.5947'N 75°46.5212'W
- Above North Colborne Island: 44° 15.4103' N 76° 4.226' W

Conditions will be monitored closely and Mariners will be advised of any changes.

April 18, 2024