



The Great Lakes - St. Lawrence Seaway System
Le réseau Grands Lacs - Voie maritime du Saint-Laurent

2025 - NOTICE TO SHIPPING #36

MAISONNEUVE REGION
MONTREAL / LAKE ONTARIO SECTION

Low Water Levels Below St. Lambert Lock

Due to the low water levels below St. Lambert Lock, ships may be below the fender when using the approach wall to make their entry into the lock. Navigators should exercise caution, and plan their approach and meets accordingly.

November 5, 2025